

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2021

Submitted Date:

03/01/2021

Document Number:

692403103

FIELD INSPECTION FORM

Loc ID 335079 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10531
Name of Operator: GRIZZLY OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott	970 876-1959	sgghan@grizzlyenergyllc.com	SR. EH&S
		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
54	WELL	PR	04/17/2008	GW	045-15433	SCOTT 34A-25-692	RI
275249	WELL	PR	10/01/2018	GW	045-13498	SCOTT 24B-25-692	RI
275250	WELL	PR	07/28/2005	GW	045-13499	SCOTT 34C-25-692	RI
275864	WELL	PR	07/27/2005	GW	045-10393	SCOTT 24D-25-692	RI
275866	WELL	PR	04/06/2008	GW	045-10391	SCOTT 24C-25-692	RI
292244	WELL	PR	04/17/2008	GW	045-14653	SCOTT 34B-25-692	RI
292245	WELL	PR	04/14/2008	GW	045-14652	SCOTT 34D-25-692	RI
292246	WELL	PR	04/25/2008	GW	045-14651	SCOTT 33A-25-692	RI
292247	WELL	PR	03/03/2016	GW	045-14650	SCOTT 24A-25-692	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed remain applicable.

Inspected FacilitiesFacility ID: 54 Type: WELL API Number: 045-15433 Status: PR Insp. Status: RIFacility ID: 275249 Type: WELL API Number: 045-13498 Status: PR Insp. Status: RIFacility ID: 275250 Type: WELL API Number: 045-13499 Status: PR Insp. Status: RIFacility ID: 275864 Type: WELL API Number: 045-10393 Status: PR Insp. Status: RIFacility ID: 275866 Type: WELL API Number: 045-10391 Status: PR Insp. Status: RIFacility ID: 292244 Type: WELL API Number: 045-14653 Status: PR Insp. Status: RIFacility ID: 292245 Type: WELL API Number: 045-14652 Status: PR Insp. Status: RIFacility ID: 292246 Type: WELL API Number: 045-14651 Status: PR Insp. Status: RIFacility ID: 292247 Type: WELL API Number: 045-14650 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured Pass 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Snow melt is occurring; visible vegetation in Interim areas appears sparse and very weedy, showing effects of high animal impact/heavy grazing pressure. Site will need to be assessed in 2021 growing season.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------	--	--

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692403104	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5364120