

TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619**



Location has impoundment of storm water.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619**



Drain crossing road. Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).



Ditch needs maintained.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619**



Drain crossing road. Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).



Ditch needs maintained.

TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619



Ditch needs maintained.



Ditch needs maintained.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619**



No evidence of tracking BMPs. Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619**



Ditch needs maintained.



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619**



Culvert (39.53184 108.13021) Culvert basin needs maintained.



Culvert basin needs maintained.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8NWSW
Location # 335619**



Ditch needs maintained.



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**