


TEP ROCKY MOUNTAIN LLC

CHEVRON-66S96W 8SESE

Location # 335634



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634**



**Flattened water hose off the edge of
location.**



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634**



**Storm water draining over edge of access road
down eroded creek bank of Parachute Creek.**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634**



**Storm water draining over edge of access road
down eroded creek bank of Parachute Creek.**

TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 8SESE
Location # 335634



Access road along eroding creek bank.



Parachute Creek