

Inspection Photos

API: 071-08810

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/1/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021

Inspection Photos



Photo 1. Facing north along the access road. The access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021

Inspection Photos



Photo 2. There is erosion along the switch back of the road. Stormwater is not being properly directed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021

Inspection Photos



Photo 3. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021

Inspection Photos



Photo 4. Facing back southeast along the access road. There is signs of erosion along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021

Inspection Photos



Photo 5. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021

Inspection Photos



Photo 6. Facing northeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021

Inspection Photos



Photo 7. Facing northeast at center of the location. Vegetation has not established. Additional seeding will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08810 | Date: 3/1/2021