

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2021

Submitted Date:

03/02/2021

Document Number:

696104425

FIELD INSPECTION FORM

Loc ID: 306018 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284699	WELL	PR	11/01/2020	GW	123-23853	ERICKSON A 8-2	SI

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Shut-In | SI.
Battery: Active.

Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150).
(Well(s): 4: Producing | PR ; 2: Shut-In | SI).

Location

Lease Road:			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type IGNITOR/COMBUSTOR		
	Comment: Barbed wire.		
Corrective Action:			Date:
	Type SEPARATOR		
	Comment: Barbed wire. Surrounded by earth berms.		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: Iron panel.		
Corrective Action:			Date:
	Type TANK BATTERY		
	Comment: Barbed wire.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	ECD #1: Crude storage vapor line combustor. Controls crude oil tanks vapors. ECD #2: Separator vapor line combustor. Controls separator vapors. Pilots: ON		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	1: Calibration card indicates calibration within last year. Last calibration: 01/30/2021. Meter active w/ production. 2: Calibration card indicates NO calibration within last year. Inactive. Remains connected to common active pig station and riser.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	ECD scrubbers.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:


Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	<50 BBLs	CONCRETE SUMP/VAULT		
Comment:					
Corrective Action:				Date:	
Paint					
Condition					
Other (Content)					
Other (Capacity)	48 Bbls.				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ crude oil tanks.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.505620,-104.573720
Comment: Equalizer line connects 2 of 3 crude oil tanks.					
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ produced H2O vaults.					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	



Inspected Facilities

Facility ID: 284699 Type: WELL API Number: 123-23853 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/20/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 03/01/2021 at approximately 15:01 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ERICKSON A-66N64W /8NWNE Location ID: 306018 Well Name: Erickson A 8-2 API: 05-123-23853 Location County: Weld County, Colorado Weather: Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Active.</p> <p>Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150). (Well(s): 4: Producing PR ; 2: Shut-In SI).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104426	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365080