

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2021

Submitted Date:

03/02/2021

Document Number:

696104427

**FIELD INSPECTION FORM**Loc ID 306012 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                              | Comment                         |
|--------------|-------|------------------------------------|---------------------------------|
| ,            |       | NBL_DJBU_Inspections@nblenergy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 284509      | WELL | PR     | 11/01/2020  | OW         | 123-23826 | ERICKSON A 8-1 | PR          |

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Producing | PR.  
Battery: Active.

Centralized Battery serves 6 Location IDs  
(306018, 305967, 305968, 305969, 306012, 330150).  
(Well(s): 4: Producing | PR ; 2: Shut-In | SI).

Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018  
for Battery / Facility, Equipment info.

| Location   |   |        |  |                 |
|--|---|--------|--|-----------------|
| <b>Lease Road:</b>                                     |   |        |  |                 |
| Type   | Access  |        |  |                 |
| comment:   | Adequate  |        |  |                 |
| Corrective Action                                      | L   |        |  | Date:           |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                 |
| <b>Signs/Marker:</b>                                   |   |        |  |                 |
| Type   | WELLHEAD  |        |  |                 |
| Comment:   |   |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type   |   |        |  |                 |
| Comment:   | Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info. |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Emergency Contact Number:                              |   |        |  |                 |
| Comment:   |   |        |  |                 |
| Corrective Action:                                     |   |        |  | Date: _____     |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                 |
| <b>Spills:</b>   |   |        |  |                 |
| Type   | Area  | Volume |  |                 |
| In Containment: No _____                               |   |        |  |                 |
| Comment:   |   |        |  |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |  |                 |
| <b>Fencing/:</b>                                       |   |        |  |                 |
| Type   | WELLHEAD  |        |  |                 |
| Comment:   | Iron panel.   |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type   |   |        |  |                 |
| Comment:   | Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info. |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| <b>Equipment:</b>                                      |   |        |  |                 |
| Type: Ancillary equipment                              | # 0   |        |  | corrective date |
| Comment:   | Equipment removed.  |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type:  | #   |        |  |                 |
| Comment:   | Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info. |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type: Plunger Lift                                     | # 1   |        |  |                 |

|                    |                             |       |  |
|--------------------|-----------------------------|-------|--|
| Comment:           |                             |       |  |
| Corrective Action: |                             | Date: |  |
| Type: Bradenhead   | # 1                         |       |  |
| Comment:           | Appears plumbed to surface. |       |  |
| Corrective Action: |                             | Date: |  |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type                | Tank ID | SE GPS                |
|--------------------|--|----------|---------------------|---------|-----------------------|
|                    |  |          | CENTRALIZED BATTERY |         | 40.505620,-104.573720 |
| Comment:           | Centralized Battery serves 6 Location IDs<br>(306018, 305967, 305968, 305969, 306012, 330150).<br><br>Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018<br>for Battery / Facility, Equipment info. |          |                     |         |                       |
| Corrective Action: |  |          |                     |         | Date:                 |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**Facility ID: 284509 Type: WELL API Number: 123-23826 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 06/20/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 03/01/2021 at approximately 15:07 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: NOBLE ENERGY INC<br/> Location Name: ERICKSON A-66N64W /8NENE<br/> Location ID: 306012<br/> Well Name: Erickson A 8-1<br/> API: 05-123-23826<br/> Location County: Weld County, Colorado<br/> Weather: Sunny, damp from prior storm.</p> <p>While there, I observed:<br/> Well(s): 1: Producing   PR.<br/> Battery: Active.</p> <p>Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150).<br/> (Well(s): 4: Producing   PR ; 2: Shut-In   SI).</p> <p>Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 03/02/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696104428    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365081">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365081</a> |