

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2021

Submitted Date:

03/02/2021

Document Number:

696104433

**FIELD INSPECTION FORM**Loc ID 305969 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284107	WELL	PR	11/01/2020	OW	123-23752	ERICKSON A 8-8	SI

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Shut-In | SI.  
Battery: Active.

Centralized Battery serves 6 Location IDs  
(306018, 305967, 305968, 305969, 306012, 330150).  
(Well(s): 4: Producing | PR ; 2: Shut-In | SI).

Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018  
for Battery / Facility, Equipment info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type			
Comment:	Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:	Equipment removed.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.505620,-104.573720
Comment:	<a href="#">Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150).</a> <a href="#">Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info.</a>				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 284107 Type: WELL API Number: 123-23752 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: Shut-In | SI.  
Observed production valves shut.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/20/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 03/01/2021 at approximately 15:25 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: ERICKSON A-66N64W /8SENE  Location ID: 305969  Well Name: Erickson A 8-8  API: 05-123-23752  Location County: Weld County, Colorado  Weather: Sunny, damp from prior storm.</p> <p>While there, I observed:  Well(s): 1: Shut-In   SI.  Battery: Active.</p> <p>Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150).  (Well(s): 4: Producing   PR ; 2: Shut-In   SI).</p> <p>Refer to Field Inspection Report doc. #696104425 and/or Location ID #306018 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/02/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104434	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365084</a>