

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2021

Submitted Date:

03/02/2021

Document Number:

699103218

FIELD INSPECTION FORMLoc ID 428272 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

29 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evins, Bret		bret.evins@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428263	WELL	PR	08/01/2019	OW	123-35292	North Platte J-F-34HNB	PR
428265	WELL	PR	05/07/2015	OW	123-35294	North Platte J-F-34HC	PR
428274	WELL	PR	05/07/2015	OW	123-35298	North Platte J14-F11-34HNC	PR
438205	WELL	PR	05/08/2015	OW	123-39908	North Platte E-A-34HC	PR
438206	WELL	SI	11/01/2020	OW	123-39909	North Platte 14-11-34HC	PR
438207	WELL	PR	05/09/2015	OW	123-39910	North Platte E14-A11-34HNC	PR
438208	WELL	PR	05/08/2015	OW	123-39911	North Platte E-A-34HNB	PR
438209	WELL	PR	04/01/2020	OW	123-39912	North Platte 14-11-34HNB	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around wellheads needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	. "Properly dispose of oily waste in accordance with Rule 905.e."	Date:	03/12/2021
Type	TRASH		
Comment:	Trash in multiple locations, needs to be removed for good housekeeping. See attached Photos.		
Corrective Action:	Comply with Rule 606	Date:	03/12/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment in multiple locations, needs to be removed for good housekeeping. See attached Photos.		
Corrective Action:	Comply with Rule 606	Date:	03/12/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gaslift- Barbwire		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Ancillary equipment	# 2			
Comment:	Automation/ Methanol Tote			
Corrective Action:				Date:
Type: Plunger Lift	# 8			
Comment:	Appears to be leaking Master Valves			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date: 03/12/2021
Type: Bradenhead	# 8			
Comment:	Appear to be plumbed to surface.			
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER					,	
Comment:	Gaslift skid					
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Adequate	
Comment:	Berm around gaslift skid is weathered.				
Corrective Action:	Maintain secondary containment devices to comply with Rule 603.o.				Date: 03/12/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities			
Facility ID: 428263	Type: WELL	API Number: 123-35292	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 09/28/2020		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 4	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	
Facility ID: 428265	Type: WELL	API Number: 123-35294	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 02/13/2020		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: No annual updated bradenhead test. Submit Reports.			
Corrective Action:		Date:	
Facility ID: 428274	Type: WELL	API Number: 123-35298	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 02/13/2020		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: No annual updated bradenhead test. Submit Reports.			
Corrective Action:		Date:	
Facility ID: 438205	Type: WELL	API Number: 123-39908	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: No annual updated bradenhead test. Submit Reports.

Corrective Action:

Date:

Facility ID: 438206 Type: WELL API Number: 123-39909 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: No annual updated bradenhead test. Submit Reports.

Corrective Action:

Date:

Facility ID: 438207 Type: WELL API Number: 123-39910 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: 0

Comment: No annual updated bradenhead test. Submit Reports.

Corrective Action:

Date:

Facility ID: 438208 Type: WELL API Number: 123-39911 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: No annual updated bradenhead test. Submit Reports.

Corrective Action:

Date:

Facility ID: 438209	Type: WELL	API Number: 123-39912	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:

End Surf Csg Pressure: 0

Comment: No annual updated bradenhead test. Submit Reports.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 3/2/21 at approximately 0913hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte 14-34 Pad of Bonanza Creek Energy, at Location ID # 428272 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment in multiple locations, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 3/12/21.</p> <p>Trash in multiple locations, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 3/12/21.</p> <p>Berm around gaslift skid is weathered. Maintain secondary containment devices to comply with Rule 603.o. With a corrective action date of 3/12/21.</p> <p>Appears to be leaking Master Valves. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 3/12/21.</p> <p>Stained soil around wellheads needs to be removed. "Properly dispose of oily waste in accordance with Rule 905.e." With a corrective action date of 3/12/21</p> <p>Well:</p> <p>North Platte J-F-34HC has no annual updated bradenhead test. Submit Reports.</p> <p>North Platte J14-F11-34HNC has no annual updated bradenhead test. Submit Reports.</p> <p>North Platte E-A-34HC has no annual updated bradenhead test. Submit Reports.</p> <p>North Platte 14-11-34HC has no annual updated bradenhead test. Submit Reports.</p> <p>North Platte E14-A11-34HNC has no annual updated bradenhead test. Submit Reports.</p> <p>North Platte E-A-34HNB has no annual updated bradenhead test. Submit Reports.</p> <p>North Platte 14-11-34HNB has no annual updated bradenhead test. Submit Reports.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103219	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365128