

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2021

Submitted Date:

03/02/2021

Document Number:

694500269

FIELD INSPECTION FORM

 Loc ID 316767 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10282
 Name of Operator: EPHPHATHA LLC
 Address: 1314 B CENTER DR #449
 City: MEDFORD State: OR Zip: 97501
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Sullins, Cory	(310) 901-1996	csullins03@yahoo.com	
Garrison, Penny		penny.garrison@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232760	WELL	SI	08/01/2019	OW	107-06175	DRY CREEK UT HD 31 1A (PILOT HOLE)	TA

General Comment:

On 3/1/2021 COGCC Staff, Kris Neidel inspected the Dry Creek UT HD 31 #1A, API #107-06175. Weather was clear and 25 degrees. It appeared that the location had not been plowed all winter. None of the pad surface was observable due to snow coverage. Inspector walked from county road. The well was TA at the time of inspection. It appeared a pump string is in the well, No pumping unit was on the well, or observed on the location. The shed on location that contains water well (permit #66138-F) was fenced in with cyclone fencing. Well head of 107-06175, surface flowline and tank battery were all fenced with cyclone fencing. The sign at the wellhead is not compliant with rule 605.d. Signage at tank battery is not compliant with 605.e. See attached photos and Corrective Actions.

Location

Lease Road:			
Type	Main		
comment:	snow covered		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Signage at tank battery is not compliant with 605.e.		
Corrective Action:	CA date taken from COGCC corrective action matrix. Review and Comply with rule.		Date: 03/05/2021
Type	WELLHEAD		
Comment:	The sign at the wellhead is not compliant with rule 605.d.		
Corrective Action:	CA date taken from COGCC corrective action matrix. Review and Comply with rule.		Date: 03/05/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	other, Flowline. cyclone fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	cyclone fence		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	cyclone fence		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment: tank labeled both, "Motor Oil" and Crude Oil.					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:	not all of the berms was observable due to snow.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 232760 Type: WELL API Number: 107-06175 Status: SI Insp. Status: TA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500270	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365248