

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2021

Submitted Date:

02/25/2021

Document Number:

701101198**FIELD INSPECTION FORM**Loc ID 335577 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282342	WELL	PR	03/01/2019	GW	045-11742	CHEVRON 2B-4D	PR
282343	WELL	PR	03/01/2019	GW	045-11741	CHEVRON 2A-4D	PR
282345	WELL	PR	03/01/2019	GW	045-11740	CHEVRON 8B-5D	PR
282349	WELL	SI	04/01/2020	GW	045-11737	CHEVRON 8C-5D	SI
282353	WELL	SI	10/01/2020	GW	045-11734	CHEVRON 2C-4D	SI
282354	WELL	SI	09/01/2019	GW	045-11749	CHEVRON 2E-4D	SI
282355	WELL	PR	03/01/2019	GW	045-11733	CHEVRON 2D-4D	PR

General Comment:**COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at CAERUS PICEANCE LLC, CHEVRON-66S96W 4SWNW, Location # 335578 in Garfield County, Colorado.

Location is in close proximity of Parachute creek and in a High Priority Habitat Area. (Mule Deer Winter Concentration Area, Elk Winter Concentration Area)

During this inspection the following possible compliance issues were observed:

Sediment build up in perimeter ditch. Location shows signs of lack of stabilization BMP's in some areas (rutting is present). Access road shows signs of lack of stabilization BMP's in some areas (rutting is present). N39.55348 W108.11985 Erosion damage from culvert outlet. N39.55096 W108.12064 Rut damage in ditch. Water not draining off road into culvert or ditch.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 5		corrective date
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 7	
Comment:	Braden head accessible for monitoring.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 7	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282342	Type:	WELL	API Number:	045-11742	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282343	Type:	WELL	API Number:	045-11741	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282345	Type:	WELL	API Number:	045-11740	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282349	Type:	WELL	API Number:	045-11737	Status:	SI	Insp. Status:	SI
Facility ID:	282353	Type:	WELL	API Number:	045-11734	Status:	SI	Insp. Status:	SI
Facility ID:	282354	Type:	WELL	API Number:	045-11749	Status:	SI	Insp. Status:	SI
Facility ID:	282355	Type:	WELL	API Number:	045-11733	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Ditches						
Berms						
		Gravel				
Gravel						
		Ditches				
				Vehicle Tracking	Fail	
Compaction						

Comment: Sediment build up in perimeter ditch. Location shows signs of lack of stabilization BMP's in some areas (rutting is present). Access road shows signs of lack of stabilization BMP's in some areas (rutting is present). N39.55348 W108.11985 Erosion damage from culvert outlet. N39.55096 W108.12064 Rut damage in ditch. Water not draining off road into culvert or ditch.

Corrective Action: Install, maintain or provide documentation of post construction management plan or BMP's Maintain vehicle tracking BMPs on the oil and gas location or Provide proof of tracking control BMP's

Date: 03/12/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402611146	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361643
701101203	Inspection 701101198 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361637