



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: Adequate		Date: _____
Corrective Action:		

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
	Comment: Pipe		
Corrective Action:		Date:	

**Equipment:**

		# 1		corrective date
Type: Plunger Lift				
Comment:				
Corrective Action:		Date:		
Type: Bradenhead		# 1		
Comment: Appears to be plumbed to surface				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 256935 Type: WELL API Number: 001-09405 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to be plumbed to surface.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<u>Routhine inspection</u>	finkenbc	02/24/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900493	Inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5367005">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5367005</a>