

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2021

Submitted Date:

03/04/2021

Document Number:

699103226

FIELD INSPECTION FORMLoc ID 413457 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evins, Bret		bret.evins@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423532	WELL	SI	04/01/2019	GW	123-33613	North Platte 32-34	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash in multiple locations, needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	03/16/2021
Type	OTHER		
Comment:	Stained soil in several locations needs to be removed, for good housekeeping. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	03/16/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment in multiple locations, needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	03/16/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Risers are not LO/TO or Marked in multiple spots. See attached photos.		
Corrective Action:	Comply with Rule 1102.o.	Date:	03/16/2021
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
					,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Adequate	
Comment:	Berm around separators is weathered. See attached photos				
Corrective Action:	Maintain secondary containment devices to comply with 603.o.				
				Date: 03/16/2021	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:	Shares containment with crude oil tanks				
Corrective Action:					
				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					
				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.363900,-104.414000
Comment:					
Corrective Action:					
				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 423532 Type: WELL API Number: 123-33613 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Waiting on the cut and cap crew.

Corrective Action: _____

Date: _____

COGCC Comments

Comment

COGCC Inspection Report Summary
 On Thursday 3/4/21 at approximately 0844hrs, I, Inspector Adam Burns,
 Conducted an on-site inspection at North Platte 32-34 of Bonanza Creek Energy, at
 Location ID # 413457 in Weld County, Colorado.
 During this inspection the following possible compliance issues were observed:
 Unused Equipment in multiple locations, needs to be removed for good housekeeping.
 Comply with Rule 606. With a corrective action date of 3/16/21.
 Berm around separators is weathered. Maintain secondary containment devices to comply
 with 603.o. With a corrective action date of 3/16/21.
 Stained soil in several locations needs to be removed, for good housekeeping. "Properly
 dispose of oily waste in accordance with 905.e." With a corrective action date of 3/16/21.
 Risers are not LO/TO or Marked in multiple spots. Comply with Rule 1102.o. With a
 corrective action date of 3/16/21
 See attached photos.
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

User

burnsa

Date

03/04/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103227	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5367715