

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2021

Submitted Date:

02/26/2021

Document Number:

700405559**FIELD INSPECTION FORM**Loc ID 336470 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                       | Comment |
|------------------|--------------|-----------------------------|---------|
| Boulger, Levin   |              | lboulger@31operating.com    |         |
| Rosenberg, Kelly |              | kelly.rosenberg@state.co.us |         |
| Freeman, Kris    | 254-717-0435 | kfreeman@31operating.com    |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 264845      | WELL | PR     | 08/16/2003  | GW         | 103-10252 | ANT HILL UNIT WYATT 31-21 D | SI          |
| 267789      | WELL | PR     | 05/06/2003  | GW         | 103-10314 | ANT HILL UNIT 36-34D        | SI          |
| 268480      | WELL | PR     | 08/16/2003  | GW         | 103-10339 | ANT HILL UNIT 36-24 D       | SI          |

**General Comment:**

A follow up inspection of FIR document 700702078 dated 12-29-2020.

The following compliance issues are uncompleted:

- 1) Debris on location. Photos 2 to 5. Complete by 2-2-2021.

Additional compliance issues:

- 1) Chemical label is faded. Photo 6. Complete by 4-28-2021.

Location is with a CDPHE Reg 42 Limited use &amp; quality area, Rule 1202.d Mule deer severe winter range area, and a Rule 1202.d Mule deer winter concentration area.

This is a summary of inspection report 700405559.

**Location**Overall Good: ☒

|                      |                         |       |            |
|----------------------|-------------------------|-------|------------|
| <b>Signs/Marker:</b> |                         |       |            |
| Type                 | TANK LABELS/PLACARDS    |       |            |
| Comment:             |                         |       |            |
| Corrective Action:   |                         | Date: |            |
| Type                 | BATTERY                 |       |            |
| Comment:             | Sign at meter building. |       |            |
| Corrective Action:   |                         | Date: |            |
| Type                 | WELLHEAD                |       |            |
| Comment:             |                         |       |            |
| Corrective Action:   |                         | Date: |            |
| Type                 | CONTAINERS              |       |            |
| Comment:             | Label is faded.         |       |            |
| Corrective Action:   | Replace label.          | Date: | 04/28/2021 |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                     |       |            |
|--------------------|---------------------|-------|------------|
| Type               | DEBRIS              |       |            |
| Comment:           | Debris on location. |       |            |
| Corrective Action: | Remove debris.      | Date: | 02/02/2021 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                       |            |       |                 |
|-----------------------|------------|-------|-----------------|
|                       |            |       | corrective date |
| Type: Bird Protectors | # 2        |       |                 |
| Comment:              |            |       |                 |
| Corrective Action:    |            | Date: |                 |
| Type: Gas Meter Run   | # 1        |       |                 |
| Comment:              | Telemetry. |       |                 |
| Corrective Action:    |            | Date: |                 |

|                                   |                               |       |
|-----------------------------------|-------------------------------|-------|
| Type: Ancillary equipment         | # 1                           |       |
| Comment:                          | Chemical container.           |       |
| Corrective Action:                |                               | Date: |
| Type: Deadman # & Marked          | # 4                           |       |
| Comment:                          |                               |       |
| Corrective Action:                |                               | Date: |
| Type: Bradenhead                  | # 1                           |       |
| Comment:                          | Bradenhead access is present. |       |
| Corrective Action:                |                               | Date: |
| Type: Plunger Lift                | # 3                           |       |
| Comment:                          |                               |       |
| Corrective Action:                |                               | Date: |
| Type: Horizontal Heated Separator | # 1                           |       |
| Comment:                          |                               |       |
| Corrective Action:                |                               | Date: |

**Tanks and Berms:**

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| CRUDE OIL          | 3 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 3 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

Inspector Name: Moran, Rick

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 264845 Type: WELL API Number: 103-10252 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last recorded production June 2020.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 267789 Type: WELL API Number: 103-10314 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last recorded production June 2020.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 268480 Type: WELL API Number: 103-10339 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last recorded production June 2020.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           |                 |                         |                       | Material Handling And Spill Prevention |                          |         |

Comment: 5" of snow on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402612249    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363091</a> |
| 700405560    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363082">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363082</a> |