

CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWSW
Location # 335766



**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWSW
Location # 335766**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWSW
Location # 335766**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWSW
Location # 335766**



**Erosion rill along shoulder onto location
allowing sediment to move on to location.**

CAERUS PICEANCE LLC
CHEVRON-66S96W 4SSW
Location # 335766



**Sediment running onto location from
shoulder of access road.**



**Sediment running onto location from
shoulder of access road.**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWSW
Location # 335766**



Rill running down access road to lower location.

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWSW
Location # 335766**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**