

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL HAGEN-67S95W /16NESE,

Location ID: 335041



Photo #3034 from entrance to location.



Photo #3035 from entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL HAGEN-67S95W /16NESE,

Location ID: 335041



Photo #3036 Rutting present on location due to lack of stabilization



Photo #3037 Rutting present on location due to lack of stabilization

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL HAGEN-67S95W /16NESE,

Location ID: 335041



Photo #3038 Rutting present on location due to lack of stabilization



Photo #3040 No form of tracking control at entrance to location