

# Inspection Photos

API: 009-06505

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 3/3/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest standing from the county road. It was observed while passing by that there was a blackend area near the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06505 | Date: 3/3/2021

## Inspection Photos



**Photo 2.** The blacken oil spilled area is approximately 60'x20'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06505 | Date: 3/3/2021

## Inspection Photos



**Photo 3.** Facing southwest toward the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06505 | Date: 3/3/2021

## Inspection Photos



**Photo 4.** View of oily soil found near the well.



## Inspection Photos



**Photo 5.** blacken oil spilled area is approximately 60'x30'.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06505 | Date: 3/3/2021

## Inspection Photos



**Photo 6.** There is an electric cable shown at red arrow which is cut in half.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06505 | Date: 3/3/2021

## Inspection Photos



**Photo 7.** There is oil stained soil around the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06505 | Date: 3/3/2021

## Inspection Photos



**Photo 8.** The well sign is posted at wellhead. The emergency number is faded and unidentifiable.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06505 | Date: 3/3/2021