

Inspection Photos  
Operator: Williford  
API: 067-06698  
Date: 3/3/2021



Photo 1. View of the project area from the southwestern corner facing northward.



Photos 2. View of the western project area facing northward.



Photo 3. View of the reference area comprised of sagebrush shrubland with understory of grasses such as James galleta and forbs in a dormant condition at this time.