

Inspection Photos
Operator: Williford
API: 067-06771
Date: 3/3/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area facing eastward.



Photos 3. View of the western project area facing southward. Revegetation appears to be progressing in a dormant vegetative condition.



Photo 4. View of the reference area comprised of sagebrush shrubland with understory of grasses such as James galleta and forbs in a dormant condition at this time.