

Inspection Photos
Operator: Williford
API: 067-06560
Date: 3/3/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area facing eastward. Revegetation is progressing with Indian ricegrass, western wheatgrass.



Photos 3. View of the western project area facing southward.



Photo 4. View of the reference area comprised of sagebrush shrubland with understory of grasses such as James galleta and forbs in a dormant condition at this time.