

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2021

Submitted Date:

02/27/2021

Document Number:

700405579**FIELD INSPECTION FORM**Loc ID 311813 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL &amp; GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229723	WELL	SI	11/01/2019	OW	103-07380	LITTLE GILLIAM 1	SI

**General Comment:**

A follow up inspection of FIR document 700404781 dated 12-28-2021.

The following compliance issues are uncompleted:

- 1) Report past due monthly operations on Form 7. Complete by 1-11-2021.

Additional compliance issues:

- 1) Gas venting out casing open to the atmosphere. Photos 3 & 4. Complete by 2-28-2021.

The emergency number 800-209-9762 was called on 2-26-2021 @ 3:02p to report the gas venting.

Location is with a Rule 1202.d Mule deer severe winter range area and a Rule 1202.d Mule deer winter concentration area.

This is a summary of inspection report 700405579.

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	Casing open to atmosphere.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Gas venting out open casing. Gas odor detected 30' from well. See attached FLIR videos & pictures.		
Corrective Action:	Comply with Rule 903.d.(3) for venting of gas.		Date: 02/28/2021

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 229723 Type: WELL API Number: 103-07380 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production October 2019.

Corrective Action: Submit required Form 7(s) to COGCC.

Date: 01/11/2021

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: 3" of snow on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Calm Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: \_\_\_\_\_ Temperature: (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
9:25	AM	9:30	AM	Wellhead(s)

Comment: FLIR camera used to capture video of gas venting from open casing.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402612302	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363143">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363143</a>
700405580	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363137">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363137</a>
700405581	FLIR HSM video of gas venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363138">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363138</a>
700405582	FLIR video of gas venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363139">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5363139</a>