

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: Adequate

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: iron

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Submersible Pump # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 238639 Type: WELL API Number: 123-05502 Status: TA Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: LYNS

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 04/19/2019

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: No PSI gauges are displayed on tubing, casing, or bradenhead to determine PSI

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine UIC inspection. No corrective actions were observed at the itme of inspection.</u> <u>**Weather Conditons: sunny, dry ground</u>	santistb	03/08/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603727	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5370598