

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2021

Submitted Date:

03/08/2021

Document Number:

699502361

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
320061 _____ MEDINA, JUSTIN _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 10395 _____
Name of Operator: GOODWIN ENERGY MANAGEMENT LLC
Address: 740 S OGDEN STREET
City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80209 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 _____ Number of Comments
1 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|---------|
| Goodwin, Scott | (303) 478-4800 | scottgoodwinjr@gmail.com | |
| Abrams, Deborah | | deborah.abrams@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 202464 | WELL | SI | 08/01/2018 | OW | 001-07869 | BOWEN-AMOCO 44-08 | SI |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: [AG fencing](#)

Corrective Action:

Date: _____

Equipment:

| Type | # | Comment | Corrective Action | Date | corrective date |
|-----------------------------|-----|----------------------------|-------------------|------|-----------------|
| Bird Protectors | # 1 | | | | |
| | | | | | |
| Prime Mover | # 1 | Gas motor | | | |
| | | | | | |
| Horizontal Heated Separator | # 1 | | | | |
| | | | | | |
| Bradenhead | # 1 | | | | |
| | | | | | |
| Gas Meter Run | # 1 | | | | |
| | | | | | |
| Pump Jack | # 1 | | | | |
| | | | | | |
| Ancillary equipment | # 1 | automation | | | |
| | | | | | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|
| | | | | | |

| | | | | | |
|--------------------|---|----------|-----------|--|-------|
| PRODUCED WATER | 1 | 300 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|----------------------------------|---------------------|-------------|
| | | | | |
| Comment: | | shares containment with oil tank | | |
| Corrective Action: | | | | |
| | | Date: | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 2 | 400 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | Date: | | |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 202464 Type: WELL API Number: 001-07869 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well has been shut in since 8/1/18 needs MIT per Mechanical integrity test rules. Violation linked to warning letter document # 402493101. Contact COGCC engineering

Corrective Action: Well must be either:
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or
2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Date: 03/08/2021

BradenHead

Date of Last Brhd Test: 05/12/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary On 3/8/21 at approximately 1500 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Bowen Amoco 44-08 Company Name- Goodwin Energy Management LLC API- 05-001-07869 In Adams County Colorado. While there, I observed SI well During this inspection the following possible compliance issues were observed: Well has been shut in since 8/1/18 needs MIT per Mechanical integrity test rules. Violation linked to warning letter document # 402493101. Contact COGCC engineering. Well must be either: 1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or 2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report. 3/8/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | medinaj | 03/08/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 699502362 | pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5371089 |