

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



Battery sign not legible and is not at tank battery.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



Battery sign is not at tank battery.



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



2 sticks of tubing laying between access road and location.



2 sticks of tubing laying between access road and location.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



2 sticks of tubing laying between access road and location.



2 sticks of tubing laying between access road and location.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



**Culvert needs maintained.
39.52242 108.13237**



**Culvert needs maintained.
39.52242 108.13237**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



**Culvert needs maintained.
39.52242 108.13237**



**Culvert needs maintained.
39.52242 108.13237**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



Ditch needs maintained.



Tire ruts in roadside ditch.