

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #3084 from entrance to location.



Photo #3085 from entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #3086 Rutting present on location due to lack of stabilization.



Photo #3087 3086 Rutting present on location due to lack of stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #3088 3086 Rutting present on location due to lack of stabilization.



Photo #3089 No form of tracking control at entrance to location.