

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2021

Submitted Date:

03/09/2021

Document Number:

700702407

FIELD INSPECTION FORM

 Loc ID 334736 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291185	WELL	PR	02/29/2008	GW	045-14320	CHEROKEE MOUNTAIN ESTATES 3-14C (N3E)	PR
291187	WELL	PR	02/06/2008	GW	045-14319	CHEROKEE MOUNTAIN ESTATES 3-14D (N3E)	PR
291191	WELL	PR	03/19/2008	GW	045-14318	CHEROKEE MOUNTAIN ESTATES 3-14B (N3E)	PR
292499	WELL	PR	01/31/2008	GW	045-14746	CHEROKEE MOUNTAIN ESTATES 3-15 (N3E)	PR
292501	WELL	PR	02/09/2008	GW	045-14747	CHEROKEE MOUNTAIN ESTATES 10-3 (N3E)	PR
293735	WELL	PR	01/29/2008	GW	045-15124	CHEROKEE MOUNTAIN ESTATES 3-15A (N3E)	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 3/9/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus N3E, at Location # 334736 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within a CPW Density/High Priority Habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of new rule 605.e
2. Well head cellars do not provide egress for wildlife. Rat holes also have access for wildlife to enter. Old broken pallet (debris) is covering on rat hole

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Well head cellars do not provide egress for wildlife. Rat holes also have access for wildlife to enter. Old broken pallet (debris) is covering on rat hole		
Corrective Action:	Provide egress for wildlife or remove possibility of wildlife to enter		Date: 03/30/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Vertical Heated Separator	# 6		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank in tank battery containment		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shared containment with condensate tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291185	Type:	WELL	API Number:	045-14320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291187	Type:	WELL	API Number:	045-14319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291191	Type:	WELL	API Number:	045-14318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	292499	Type:	WELL	API Number:	045-14746	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	292501	Type:	WELL	API Number:	045-14747	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293735	Type:	WELL	API Number:	045-15124	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
		Rip Rap				
		Sediment Traps				
Ditches						
Other						rock retaining wall on cut slope
		Culverts				

Comment: This location is within a CPW Density/High Priority Habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702410	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5371821