

# Inspection Photos

API: 009-06628

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/3/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 1.** Facing northeast at the beginning of the access road. The access road has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 2.** Facing east at the access road near the location. It appears mulch was applied to the area of access road near the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 3.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 4.** Facing toward the northwest side. The fill slope has not been recontoured.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 5.** Facing northeast at the location. Vegetation is not establishing at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 6.** Facing east at the north side of the location. This area is approximately 150'x100' with no vegetation. It appears there is soil issues preventing vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 7.** Facing west at the north side of the location. This area is approximately 150'x100' with no vegetation. It appears there is soil issues preventing vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 8.** Facing south at the east side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 9.** Facing west at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 10.** Facing south toward the surrounding undisturbed reference area.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021

## Inspection Photos



**Photo 11.** Aerial image of the access road and location. Arrow points to the beginning of the access road which needs to be reclaimed to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06628 | Date: 3/3/2021