

Inspection Photos

API: 009-06439

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06439 | Date: 3/3/2021

Inspection Photos



Photo 1. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 3/3/2021

Inspection Photos



Photo 2. There is a pipe riser and electric utility that remains at the east side of the location. All equipment should have been removed within 3 months of abandoning the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 3/3/2021

Inspection Photos



Photo 3. Facing southwest at the location. The location has not been reclaimed. Vegetation does not meet 80% standard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 3/3/2021

Inspection Photos



Photo 4. Facing east of the equipment shown in previous photo. It appears disturbance occurred out east of the well. This area needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 3/3/2021

Inspection Photos



Photo 5. Facing northeast at the east side of the location. Pipe riser and electric utility needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 3/3/2021

Inspection Photos



Photo 6. Facing northeast. Guy line anchor remains at the southwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 3/3/2021