

Inspection Photos

API: 009-06682

Operator: MEADOW DEEP LLC

Inspection Date: 3/3/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021

Inspection Photos



Photo 1. Facing southeast toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021

Inspection Photos



Photo 2. The access road dead ends at the location. The access road needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021

Inspection Photos



Photo 3. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021

Inspection Photos



Photo 4. Center of the location facing east. Vegetation is uniformly established at the location consisting predominately of Sand dropseed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021

Inspection Photos



Photo 5. Center of the location facing north.



Inspection Photos



Photo 6. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021

Inspection Photos



Photo 7. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021

Inspection Photos



Photo 8. Facing south toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06682 | Date: 3/3/2021