

Inspection Photos

API: 071-06347

Operator: OGRIS OPERATING LLC

Inspection Date: 3/8/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06347 | Date: 3/8/2021

Inspection Photos



Photo 1. There is sediment deposition onto the main road. Stormwater is not properly diverted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 3/8/2021

Inspection Photos



Photo 2. The culvert shown at red arrow is filled in with sediment. Stormwater is not directed toward the culvert and is flowing down the road. Lat/Long:37.06585,-104.93198.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 3/8/2021

Inspection Photos



Photo 3. Facing west along main road near the location. Stormwater is not directed toward the culvert and is pooling on the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 3/8/2021

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 3/8/2021

Inspection Photos



Photo 5. Sign posted on meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 3/8/2021