

Inspection Photos

Loc#335636

Operator: Terra

Insp#: 692403178

Insp Date: 3/5/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View over Location to South

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335636



Photo#2:
Excess stockpile at entrance to lower location.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335636



Photo#3:

View back South to Excess Stockpile in Photo #1. Stockpile indicated by arrow is labeled Topsoil. Insert, view along damaged wattles at base of Topsoil pile. Note rutting caused accessing Excess Stockpile.

March 5, 2021



Photo#4:
Sediment migration & erosion on Cut slope.

March 5, 2021



Photo#5:
Sediment migration & erosion on Cut slope.



Photo#6:
Erosion, degradation of Fill slopes.

Photo#7:
Erosion, degradation of Fill slopes.

March 5, 2021




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335636



Photo#8:
Topsoil pile along road to lower Location. Note damaged wattles.



Photo#9:
Topsoil pile along road to lower Location

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335636



Photo#10:
Rutting on portions of pad.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335636



Photo#11:
BMPs needing repair/maintenance.



Photo#12:
BMPs needing repair/maintenance

March 5, 2021



Photo#13:
BMPs needing repair/maintenance.



Photo#14:
BMPs needing repair/maintenance

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335636



Photo#15:
Cuttings area.

March 5, 2021



Photo#16:
Cuttings area.