

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2021

Submitted Date:

03/10/2021

Document Number:

690201259

FIELD INSPECTION FORM

Loc ID 307299 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		rmack@ogrisop.com	
		efitzgerald@ogrisop.com	
		timothy.thomsen@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217414	WELL	PR	05/06/2020	GW	071-06191	APACHE CANYON 20-5	RI

General Comment:

This is a follow up of the previous inspection number 690200861.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type			
Comment:	Good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	The steel grates around the wellhead do not completely cover the area around the well. This could be a potential hazard for wildlife entry.		
Corrective Action:	Cover and protect the area around the wellhead to prevent entry.	Date:	03/12/2021
Type	OTHER		
Comment:	There is oil and oily rags in the engine skid that need to be cleaned up.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area.	Date:	03/12/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The cattle guard along the main road is filled in with sediment and is not maintained. There are areas along the main road where stormwater is not diverted toward the culvert which is creating vehicle rutting and pooling on the road. Areas of rutting along the road need to be repaired and stabilized with gravel. Previous corrective action was not performed. Corrective action needs to be performed immediately to obtain compliance. Additionally, there is vehicle rutting west of the well site where the drip line is located.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C**

Date: 12/23/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201260	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372910