

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2021

Submitted Date:

03/11/2021

Document Number:

690102320

FIELD INSPECTION FORM

Loc ID: 320294 Inspector Name: Maclaren, Joe On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
 Address: 1001 17TH STREET #2000
 City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@gwogco.com	
Canfield, Chris		chris.canfield@state.co.us	
Davidson, Jason		j davidson@gwp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203377	WELL	PR	11/01/2019	GW	001-08886	REHFELD K UNIT 1	EG

General Comment:

COGCC Engineering Integrity/ Flowline Inspection
 Photos uploaded

Inspected Facilities

Facility ID: 203377 Type: WELL API Number: 001-08886 Status: PR Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: _____ Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC Integrity Inspector on location on 3/04/2021; Inspector spoke with GWOC personnel in the process of removing wellhead, dump and process flowlines previously servicing the Rehfeld K Unit 1. Well has been plugged and abandoned; cut and cap activities at wellhead are pending. COGCC form 42 start of plugging operations doc #402605474 received on 02/22/2021. Flowlines have been excavated and removed from ground between wellhead, production equipment and tank battery. COGCC form 42 flowline pre abandonment 30-day notice doc #402601788 received on 02/17/2021.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
As outlined in the CA section of COGCC form 19 doc #402614111 submitted on 03/03/2021: Potential impacts to soil and shallow groundwater were observed beneath the separator during facility closure activities on 3/1/21, and 170 feet east of the separator, beneath the partially buried produced water tank on 3/2/21. The exact cause is unknown; horizontal separator and partially buried produced water tank. Excavation and remediation activities are currently in progress.	maclarej	03/11/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102332	Well (plugged; pending cut cap) and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5373675
690102333	View of location; looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5373676