

**Inspection Photos**  
**Operator: Logos Operating**  
**API: 067-08098**  
**Date: 3/9/2021**



Photo 1. View of the project area from the western edge facing center. Revegetation is conducted in portions of the well pad identified during 2019 reclamation inspection, continued monitoring and management is needed. Russian thistle debris needs to be removed and managed.



Photo 2. View of the northern project area facing eastward.



Photos 3. View of the western project area facing southward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland, with understory of grasses and forbs such as Palmer's penstemon and Indian ricegrass.