

Inspection Photos
Operator: Simcoe
API: 067-08408
Date: 3/9/2021



Photo 1. View of the project area from the southwestern edge facing center. Revegetation is conducted in portions of the well pad identified during 2019 reclamation inspection, continued monitoring and management is needed. Russian thistle debris needs to be removed and managed.



Photo 2. View of the western project area facing southward. Revegetation is progressing with sand dropseed, western wheatgrass, and rubber rabbitbrush. Dense Russian thistle debris observed along the western diversion.



Photos 3. View of the southeastern project area facing southward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland, with understory of grasses and forbs such as Palmer's penstemon and Indian ricegrass.