

Inspection Photos
Location Name: Bentley 11-25
Location: 324025



Lease road entry from CR 301



Lease road looking SE From CE 301.

Inspection Photos
Location Name: Bentley 11-25
Location: 324025



Location shows inconsistent stabilization



Tracking occurring from location onto the lease road.

Inspection Photos
Location Name: Bentley 11-25
Location: 324025



Storm Water is impounded, and saturating the soil along the pad edge and lease road used to access facility # 268858



SW run-on and sediment are impeded by the production tank battery berm at the south corner of location

Inspection Photos
Location Name: Bentley 11-25
Location: 324025



Storm water is allowed to move across location and lease road at the west side of location.



Storm water run off is causing migration of sediment from the pad surface to the vegetated areas on the North side of location.