

Inspection Photos
Location Name: Harris
Location: 311678



Location at the Entry



Location Entry

Inspection Photos
Location Name: Harris
Location: 311678



Vehicle Storage at the North corner of location



Tank stored on the East edge of lease

Inspection Photos
Location Name: Harris
Location: 311678



Slope not stabilized on the South cut slope



Large Rocks are falling off of cut slope onto the pad.

Inspection Photos
Location Name: Harris
Location: 311678



Slope not stabilized on the East cut slope



Unused areas of pad have not been stabilized or reclaimed.

Inspection Photos
Location Name: Harris
Location: 311678



Trash and Debris in the South corner of this pad



Trash near production equipment.

Inspection Photos
Location Name: Harris
Location: 311678



Lease road not stabilized