

Inspection Photos

API: 071-06128

Operator: OGRIS OPERATING LLC

Inspection Date: 3/8/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 3/8/2021

Inspection Photos



Photo 1. This culvert along the main road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 3/8/2021

Inspection Photos



Photo 2. There is a plugged culvert along the main road (red arrow) causing stormwater to flow down the road. Lat/Long:37.09178,-104.93688. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 3/8/2021

Inspection Photos



Photo 3. The culvert is filled in with sediment causing stormwater to flow down the road. All culverts need to be maintained. Previous corrective action was not performed. The culverts need to be cleaned out once snow melts.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 3/8/2021

Inspection Photos



Photo 4. There is vehicle ruts occurring after repairs had been performed. BMP's such as gravel is needed to prevent rutting and road degradation. Grading alone is not sufficient.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 3/8/2021

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 3/8/2021