

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	location entrance are adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 262596 Type: WELL API Number: 123-20764 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: Pioneer Energy Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7910 Cement Volume (sx): 2

Good Return During Job: YES Cement Type: G

Comment: Arrived on location at 1045 hrs., Pioneer energy services on location RU and running gage log. POOH and PU CIBP, RIH and set at 7910 ft. with 2 sxs neat cement on top. POOH

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/11/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 295 Fluid Type: GAS
 End Surf Csg Pressure: 1

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 3/12/2021 at approximately 1045 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location: Ballantine 4-30A at API #05-123-20764 in Weld County Colorado. While there, I observed a Plugging operation, Form 42 Doc # 402620325 submitted on 3-8-2021. During this inspection no compliance issues were observed: See attached photos. Location: wet, Weather: cloudy. I spoke with Dave McGruder Well Site Supervisor with Kerr McGee about the upcoming weather, BMPs, well logs and plug depths. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	03/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303605	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375333