



Whiting Oil & Gas Corporation

WILDHORSE 18-1834H CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 430306
Section 18 T9N R59W

3-12-2021



Unused Parts/Equipment at Wellhead Have Been Removed



Whiting Oil & Gas Corporation

WILDHORSE 18-1834H CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 430306
Section 18 T9N R59W

3-12-2021



Workover Rig Equipment Removed