

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2021

Submitted Date:

03/12/2021

Document Number:

696104452**FIELD INSPECTION FORM**Loc ID 415365 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|---------------------------------|
| , | | NBL_DJBU_Inspections@nblenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 415430 | WELL | TA | 03/25/2020 | OW | 123-31070 | 70 RANCH USX BB 25-07P | TA |

General Comment:

This is an Alternate Method Inspection | AMI.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Abandoned. ALL equipment has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.372676 / -104.379643

Location

| | | | |
|--------------------|----------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|--|-------------|
| Emergency Contact Number: | | |
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. Metal berms surround wellsite. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears plumbed to surface. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 415430 Type: WELL API Number: 123-31070 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned: All Equipment Removed.
COGCC records indicate last production: 05/2018.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Form 4 Sundry doc. #402617741, Temporarily Abandoned | TA status date: 10/01/2018.
Approval Pending.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 08/26/2019 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: --

Comment: No record of Brhd test within last 12 months. Refer to Rule 206.
Submit current Brhd test. Comply w/ Rule 419.b.(5).
Contact COGCC Engineering.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On FRI 03/12/2021 at approximately 15:35 hrs. I, Bret Evins, conducted an Alternate Method Inspection AMI at: Operator Name: NOBLE ENERGY INC Location Name: 70 RANCH USX BB /25-07P Location ID: 415365 Well Name: 70 Ranch USX BB 25-07P API: 05-123-31070 Location County: Weld County, Colorado Weather: Overcast, damp from prior storm.</p> <p>Observations from prior on-site inspection: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment removed except for Gas meter run & riser. Abandoned Battery SE corner GPS coordinates: 40.372676 / -104.379643</p> <p>Prior Corrective Action for Unused Equipment (Gas meter run & riser) cleared. More than 1 year has elapsed since prior insp. (11/12/2019). Field Inspection Response Resolution FIRR doc. #402617872 indicates Unused Equipment Gas meter run & riser) has been removed as of 03/02/2021 per company provided photo.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 03/12/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------|---|
| 696104453 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375412 |
| 696104454 | FIRR Company provided photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375413 |