

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2021

Submitted Date:

03/12/2021

Document Number:

699802756

FIELD INSPECTION FORMLoc ID 334358 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285162	WELL	PR	10/14/2006	GW	045-12389	JOLLEY 3-12 (OK3)	PR
285163	WELL	PR	11/02/2006	GW	045-12388	JOLLEY 3-12A (OK3)	PR
285165	WELL	PR	10/19/2006	GW	045-12387	JOLLEY 3-11A (OK3)	PR
285166	WELL	PR	10/17/2006	GW	045-12386	JOLLEY 3-11 (OK3)	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 3/12/21 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted, a follow up inspection at CAERUS PICEANCE LLC JOLLEY-68S96W /3NESW, Location #334358 in Garfield County Colorado.

While there, I observed normal production operations.

Refer to document #699802395 inspection conducted on 1/11/21. All previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Location lacks stabilization. See photo #3129, #3130 and #3131. No form of tracking control at entrance to location. See photo #3132 with a corrective action date of 3/27/21. Location is located on the edge of a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Note there is no battery sign located at the battery. The previous information was posted on the tanks and does not meet the new battery sign requirements of Rule 605 e.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead signs located at separators not wellheads		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:	Summit midstream	
Corrective Action:		Date:
Type: Bradenhead	# 4	
Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	285162	Type:	WELL	API Number:	045-12389	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285163	Type:	WELL	API Number:	045-12388	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285165	Type:	WELL	API Number:	045-12387	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285166	Type:	WELL	API Number:	045-12386	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						By wellheads
Compaction	Fail					Location lacks stabilization
Ditches						
		Ditches				
		Berms				
		Culverts				
		Check Dams				
Sediment Traps						
		Gravel				
Berms						
		Compaction				

Comment: Location lacks stabilization. See photo #3129, #3130 and #3131. No form of tracking control at entrance to location. See photo #3132. Location is located on the edge of a high priority habitat area.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 03/27/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	03/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802757	Photos for Insp. #699802756	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5376024