

Inspection Photos
Operator: Simcoe
API: 067-08883
Date: 3/10/2021



Photo 1. View of the eastern project area from the southeastern corner facing northward. Revegetation appears to be progressing with grasses such as crested wheatgrass, intermediate wheatgrass, and western wheatgrass.



Photo 2. View of the southern project area from the southeastern corner facing westward. Sparse revegetation observed in portions of the fill slope where spot seeding may be needed.



Photo 3. View of the access road facing westward.



Photo 4. View of reference area comprised of open pinyon-juniper woodland with sagebrush and western wheatgrass, blue grama, and other grasses forbs in a dormant condition.



Photo 5. View of closed gate after leaving location.