

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2021

Submitted Date:

03/08/2021

Document Number:

699802725

**FIELD INSPECTION FORM**Loc ID 334579 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284675	WELL	PR	05/10/2006	GW	045-12253	BOSELY SG 524-23	PR
284676	WELL	PR	05/10/2006	GW	045-12252	BOSELY SG 424-23	PR
284677	WELL	PR	05/10/2006	GW	045-12251	BOSELY SG24-23	PR
284678	WELL	PR	05/10/2006	GW	045-12250	BOSELY SG 324-23	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 3/8/21 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW, Location #334579 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Rutting present on location due to lack of stabilization. See photo #3086, #3087 and #3088. No form of tracking control at entrance to location. See photo #3089 with a corrective action date of 3/23/21. Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign located at separator and not tank battery. Battery sign weathered but still legible.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign weathered but still legible		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 4			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 4			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 4			
Comment:	All meter runs have been calibrated in the last year			
Corrective Action:				Date:
Type: Bradenhead	# 4			
Comment:	No form of pressure monitoring equipment located at braden heads. All braden head valves are accessible.			
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284675	Type:	WELL	API Number:	045-12253	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284676	Type:	WELL	API Number:	045-12252	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284677	Type:	WELL	API Number:	045-12251	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284678	Type:	WELL	API Number:	045-12250	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						
		Culverts				
		Berms				
Gravel						by wellheads
		Compaction	Fail			Rutting present on access road
		Ditches				
Compaction	Fail					Rutting present on location
		Gravel				
Other	Fail					No form of tracking control

Comment: [Rutting present on location due to lack of stabilization. See photo #3086, #3087 and #3088. No form of tracking control at entrance to location. See photo #3089. Location is located in a high priority habitat area.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 03/23/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Storm water for corrective actions.</a>	depaoloc	03/08/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402622591	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5371193">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5371193</a>
699802726	Photos for Insp. #699802725	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5371188">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5371188</a>