

# Huber Rhoads 4 #33

Corrective Actions Taken on the Huber Rhoades 4 #33 for COGCC  
Compliance INC.

# Huber Rhoads 4 #33

03/12/21



Storm Water management controls have been installed and re-established to stabilize erosion. Re-established drainage diversion on the east side of pad. Re-contoured drainage, repaired erosion cuts, installed silt traps, and rock rundowns to de-energize storm water run off. Spot seeded disturbed and barked areas on southeastern fill slope.







