

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2021

Submitted Date:

03/10/2021

Document Number:

701002531

FIELD INSPECTION FORM

Loc ID 303527 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

12 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253242	WELL	PR	08/01/2019	GW	125-07119	ECKLEY OIL & LAND 2-13	PR

General Comment:

Routine Inspection

Location

Lease Road:			
	Type	Access	
	comment:	Gravel road through pasture	
	Corrective Action:		Date:

Overall Good:

Signs/Marker:			
	Type	TANK LABELS/PLACARDS	
	Comment:	Metal sign by water tank	
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:	Lease sign by meter shed	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Wire paenls around wellhead and meter shed	
	Corrective Action:		Date:
	Type	TANK BATTERY	
	Comment:	Metal panels around water tank	
	Corrective Action:		Date:

Equipment:			corrective date
Type:	Vertical Separator	# 1	
	Comment:	Vertical gas separator 50% buried by wellhead	
	Corrective Action:		Date:
	Type:	Gas Meter Run	
	Comment:	# 1	
	Corrective Action:		Date:
	Type:	Ancillary equipment	
	Comment:	Telemetry equipment	
	Corrective Action:		Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.885970,-102.244400
Comment: Fiberglass water tank 50% buried next to meter shed					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)	214bbbs				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms will need maintenance					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 253242 Type: WELL API Number: 125-07119 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Welp 33-13, 34-13 & Eckley Oil & Land 2-13\) 2200' S @ 39.88010/-102.24566](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
		Compaction	Fail			

Comment: [Location and access have erosion](#)

Corrective Action: [Repair and maintain erosion](#)

Date: 04/08/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402624389	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372619
701002561	Location and access photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372609