

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2021

Submitted Date:

03/17/2021

Document Number:

688309998

FIELD INSPECTION FORM

Loc ID 336785 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Foundation, Energy	(866) 767-3600	regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279304	WELL	PR	09/24/2005	GW	125-09415	WAKEFIELD 12-30	PR

General Comment:

[Routine Inspection](#)
[Stained soil at wellhead \(see attached photo\).](#)

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	lease sign at CR V		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	866-767-3600	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date
Vertical Separator	# 1	partially buried		
Gas Meter Run	# 1	digital, 10/20 calibration card		
Bird Protectors	# 1	cover on electric motor		
Bradenhead	# 1			
Pump Jack	# 1			

Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

--

Location Construction

Location ID: 279304 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 279304 Type: WELL API Number: 125-09415 Status: PR Insp. Status: PR

Producing Well

Comment: [PR 1/1/2021 production reported to COGCC database.](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688310024	Foundation Wakefield 12-30	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5378610