



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 451242 Type: WELL API Number: 123-45037 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On (3/17/21) at approximately (10:35 HRS), I, Inspector (Abe Serna),  Conducted an on-site inspection at (Fed Library 20W-25-18) (Extraction Oil &amp; Gas), at  (API #123-45037) in (Weld County) Colorado.  While there, I observed a (PR Well)  During this inspection no compliance issues were observed  No follow up on this site inspection needs to be conducted.  This is a summary of inspection report.  Snow covered ground.</p>	sernaa	03/17/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698702608	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5378867">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5378867</a>