

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2021

Submitted Date:

03/11/2021

Document Number:

692700032

FIELD INSPECTION FORM

Loc ID 324025 Inspector Name: KELLERBY, SHAUN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Longworth, Mike		michael.longworth@state.co.us	
De Paolo, Corey		corey.depaolo@state.co.us	
Ramsey, Scott		scott.ramsey@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211522	WELL	PR	08/01/2020	GW	045-07282	BENTLEY 11-24	PR

General Comment:

Inspection was conducted due to COGCC staff observation of heavy tracking of sediment onto Garfield County road 301.

On 3/9/21, I Shaun Kellerby conducted a field inspection of facility #324025, SENE 11 7S95W, in Garfield County Colorado. I observed normal production operations.

Facility 324025 is located in a designated High Priority Habitat area, and in close proximity to USFWS wetlands inventory area, and rule 1202c NSO habitat area.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Sign not posted or information inaccurate at battery		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	04/16/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211522 Type: WELL API Number: 045-07282 Status: PR Insp. Status: PR

Producing Well

Comment: [Last reported production 12/20.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Heavy Tracking onto county road from lease road is occurring. No tracking BMP are present at the time of inspection. Run-on is not controlled, and storm water is allowed to move through location. Sediment migration is ongoing on the north side of location. Storm water from location and the main lease road is directed to the bottom of the lease road where the tracking is occurring.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/19/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402626509	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374405
692700033	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374404