

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



Photo #3158 from entrance to location.



Photo #3159 from entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



Photo #2393 from inspection #699802208 conducted on 12/4/20.



Photo #3165 1" flowline riser not LO/TO.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



**Photo #3163 Debris in perimeter ditch on Eastside of location.**



**Photo #3167 Flow line heating insulation open ended and not capped.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



**Photo #3160 Location lacks stabilization.**



**Photo #2394 from inspection #699802208 conducted on 12/4/20.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



**Photo #3161 Location lacks stabilization.**



**Photo #2395 from inspection #699802208 conducted on 12/4/20.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



**Photo #3166 No form of tracking control at entrance to location.**



**Photo #2396 from inspection #699802208 conducted on 12/4/20.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



**Photo #3164 Sediment appears to have been plowed into ditch**



**Photo #3162 Perimeter berm has been compromised.**