

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2021

Submitted Date:

03/19/2021

Document Number:

699802795

FIELD INSPECTION FORMLoc ID 334182 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277173	WELL	SI	09/01/2020	GW	045-10612	MURRAY 1-14B	SI
288414	WELL	PR	09/30/2007	GW	045-13220	MURRAY 1-14D	PR
288415	WELL	PR	09/01/2011	GW	045-13219	MURRAY 1-14C	PR
288416	WELL	PR	03/31/2008	GW	045-13218	MURRAY 1-14A	PR
288417	WELL	PR	02/29/2008	GW	045-13217	MURRAY 1-24D	PR
288418	WELL	PR	01/07/2011	GW	045-13216	MURRAY 1-24C	PR

General Comment:

COGCC Inspection Report Summary
 On Friday 3/19/21 at approximately 12:00 hours, I, Inspector Corey De Paolo,
 Conducted, an on-site inspection at CAERUS PICEANCE LLC MURRAY-68S96W /1SWW Wellhead site,
 Location #334182 in Garfield County Colorado.
 While there, I observed normal production operations.
 This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	Tank battery located on a different location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Hog panels			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Bradenhead	# 6			
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.			
Corrective Action:				Date:
Type: Plunger Lift	# 6			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Venting:				
Yes/No	NO			

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 277173 Type: WELL API Number: 045-10612 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last produced September 2020

Corrective Action: _____ Date: _____

Facility ID: 288414 Type: WELL API Number: 045-13220 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 288415 Type: WELL API Number: 045-13219 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 288416 Type: WELL API Number: 045-13218 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 288417 Type: WELL API Number: 045-13217 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 288418 Type: WELL API Number: 045-13216 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						By wellheads
		Sediment Traps				
		Ditches				
		Compaction				
		Culverts				
Berms						
Ditches						
Compaction						
		Berms				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Refer to document #699802375 for equipment inventory and tank battery information.	depaoloc	03/19/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802796	Photos for Insp. #699802795	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5381740